


**Remove this component**



**Apply this fix ONLY if:**

- your board is v2.0
- you hear a tone in stereo mode!